



## HALDIBARI MUNICIPALITY

### CONSTRUCTION SITE FIRST VISIT REPORT

First Visit: PROP - 02124 - BOLO PARA

#### Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
BOLO PARA	26.30627 88.78811	2	30	22.750 Meter

#### Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Boys	1	1	2	1

#### Land Details

Classification	Plot No.	Jl No.	Seg No.	Khatam No.	Area	Possession Details (Owned by)
Boys	98	001	0020	50, 2011	0020 HALDIBARI	

30/11/2025

Column No.	Length (M)	Width (M)	Height (M)	Status	Remarks
01	1.00	1.00	2.00	OK	OK

4

Column image



Re. reinforcement

Rebar  
(10 mm dia 10 nos each)

Reb. No.	Diameter (M)	Status	Remarks
01	10	OK	OK

Rebar image



Column  
(12 mm dia 6 nos)

Reb. No.	Diameter (M)	Length (M)	Height (M)	Status	Remarks
01	12	2.00	2.00	OK	OK

Column image



Tie beam  
(13 mm dia 4 nos)

Reb. No.	Diameter (M)	Length (M)	Width (M)	Status	Remarks
01	13	2.00	2.00	OK	OK

Tie beam image



Slender for Column 6 mm dia 175 mm C/C

Status	Remarks
OK	OK

Slender for Tie 6 mm dia 175 mm C/C

Status	Remarks
OK	OK

Overall Remarks

OK



Page 3 of 3

*[Handwritten Signature]*

Signatures & Approvals

Sub-Assistant Engineer  
Haldibari Municipality  
Haldibari, Cooch Behar

Signature of Engineer  
Name  
Contract No.

*[Handwritten Signature]*  
Co-ordinator  
Hijji INSPIRATION