



**JANGIPUR MUNICIPALITY**  
**CONSTRUCTION SITE SECOND VISIT REPORT**

Second Visit : PROP-01595 - Belchatra

**Location Details**

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Belchatra	22.5797152 88.4135183	3	22.5SqM	Sq/Meter

**Project Details**




Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	1	1	1	1

**Land Details**


Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	564	007	007	12419	Jangipore	


At the time of Roof Casting - Visit Details


Visit Date	22/02/2026											
Roof Beam Top Support (16 mm dia, 4 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Top Support Image												
Roof Beam Bottom Support (16 mm dia, 2 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Bottom Support Image												
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Mid Span Top Support Image												
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Mid Span Bottom Support Image												

Roof Details Parameters Image	 <p>Lat: 24.46927 Long: 88.08483 Location: Jangipur, Chhota</p>				
Binder for Roof Beam Support (250mm X 250mm)	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
Binder for Roof Beam Mid Span Support	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
Binder for Roof 8mm dia 125mm C/C	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
Overall Reamrks	There is no mid beam in CT 1 model drawing				
<b>Overall Work Status - Images</b>					
Photo 1 - Angle 1	 <p>Lat: 24.46927 Long: 88.08483 Location: Jangipur, Chhota</p>				
Photo 2 - Angle 2	 <p>Lat: 24.46928 Long: 88.08483 Location: Jangipur, Chhota</p>				

Signatures & Approval

  
 Sub-Asst. Engineer  
 Jangipur Municipality

  
 Coordinator  
 Hiji INSPIRATION

Checked & Verified  
  
 Engineer (Civil)  
 Hiji INSPIRATION