



JANGIPUR MUNICIPALITY
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01616 - Chhotkalia

Location Details

| Name of the Location | Latitude & Longitude | Ward | Area | Area Unit |
|----------------------|------------------------|------|----------|-----------|
| Chhotkalia | 22.57971 88.4135158 | 7 | 35.7 SqM | Sq/Meter |




Project Details



| Proposed Project Type | Toilet Seat (Male) | Toilet Seat (Female) | Urinal Seat (Male) | Urinal Seat (Female) |
|----------------------------|--------------------|----------------------|--------------------|----------------------|
| PT (Public Toilet Project) | 2 | 2 | 3 | 2 |

Land Details


| Classification | Plot No. | Jl No. | Dag No. | Khatian No. | Mouza | Possession Details (Owned by) |
|----------------|----------|--------|---------|-------------|------------|-------------------------------|
| Bastu | 1308 | 019 | 1308 | 777 | Chhotkalia | |

At the time of Roof Casting - Visit Details

| <p>Visit Date</p> | <p>22/02/2026</p> | | | | | | | | | | |
|--|--|----------|---------------|--------|---------|---|----|----|----|--|--|
| <p>Roof Beam Top Support (16 mm dia, 4 nos.)</p> | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 4 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 4 | 16 | OK | OK | | | | | | | | |
| <p>Roof Beam Top Support Image</p> |  <p>Lat: 24.46153 Long: 88.08193 Location: Jangipur, Chhota</p> | | | | | | | | | | |
| <p>Roof Beam Bottom Support (16 mm dia, 2 nos.)</p> | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 2 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 2 | 16 | OK | OK | | | | | | | | |
| <p>Roof Beam Bottom Support Image</p> |  <p>Lat: 24.46153 Long: 88.08193 Location: Jangipur, Chhota</p> | | | | | | | | | | |
| <p>Roof Beam Mid Span Top Support (16 mm dia 2 nos)</p> | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 2 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 2 | 16 | OK | OK | | | | | | | | |
| <p>Roof Beam Mid Span Top Support Image</p> |  <p>Lat: 24.46152 Long: 88.08193 Location: Jangipur, Chhota</p> | | | | | | | | | | |
| <p>Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)</p> | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 4 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 4 | 16 | OK | OK | | | | | | | | |
| <p>Roof Beam Mid Span Bottom Support Image</p> |  | | | | | | | | | | |

| Roof Details Parameters Image | |  <p>Lat: 24.46153 Long: 88.08193 Location: Jangipur, Chhota</p> | | | | |
|--|---------|---|--------|---------|----|----|
| Binder for Roof Beam Support (250mm X 250mm) | | <table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Status | Remarks | OK | OK |
| Status | Remarks | | | | | |
| OK | OK | | | | | |
| Binder for Roof Beam Mid Span Support | | <table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Status | Remarks | OK | OK |
| Status | Remarks | | | | | |
| OK | OK | | | | | |
| Binder for Roof 8mm dia 125mm C/C | | <table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Status | Remarks | OK | OK |
| Status | Remarks | | | | | |
| OK | OK | | | | | |
| Overall Remarks | | Ok | | | | |
| Overall Work Status - Images | | | | | | |
| Photo 1 - Angle 1 | |  <p>Lat: 24.46152 Long: 88.08194 Location: Jangipur, Chhota</p> | | | | |
| Photo 2 - Angle 2 | |  <p>Lat: 24.46153 Long: 88.08194 Location: Jangipur, Chhota</p> | | | | |

Signatures & Approval


 Sub- Asst. Engineer
 Jangipur Municipality


 Page 3 of 3 Co-ordinator
 Hijli INSPIRATION

Checked & Verified

 Engineer (Civil)
 Hijli INSPIRATION