



DINHATA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
PIONEER CLUB , DINHATA	26.1322003 89.4621563	6	PIONEER CLUB , MAIN ROAD DINHATA	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	3	2	3	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	8495	108	0	1204	DINHATA	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-12-05
Nearest location of CT/PT (approx)	PIONEER CLUB , DINHATA
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	3
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	2
total Baths	0
Bath	0
Area	22.7 SQM
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Toilet maintenance by club committee

Name: Narayan Barman

Designation: SAE

Contact No: 9933631763

Date: _____

Name: Abhik Majumdar

Designation: Civil Engineer

Signature with stamp

Sub Assistant Engineer,
Dinhata Municipality

Checked & Verified

Abhik Majumdar
6.12.25
Engineer (Civil)
Hijli INSPIRATION

Abhik Majumdar
6.12.25

Signature with stamp assigned by Hijli Inspiration

Site Image

