



HALISAHAR MUNICIPALITY

CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-00576 - NABA JAGARAN SANGHA, HALISAHAR EAST KABIRAJ PARA, NORTH 24 PARAGANAS

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
NABA JAGARAN SANGHA, HALISAHAR EAST KABIRAJ PARA, NORTH 24 PARAGANAS	22.5797281 88.4135406	14	45	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Bastu	1	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	06	09	06	0	BALIBHARA	

At the time of Roof Casting - Visit Details

Visit Date	03/12/2025											
Roof Beam Top Support (16 mm dia, 4 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Top Support Image												
Roof Beam Bottom Support (16 mm dia, 2 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Bottom Support Image												
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Mid Span Top Support Image												
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Mid Span Bottom Support Image												
Roof Details Parameters (8 mm dia 125 nos)	<table border="1"> <thead> <tr> <th>Diameter (mm)</th> <th>Depth (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> </tbody> </table>	Diameter (mm)	Depth (mm)	Status	Remarks							
Diameter (mm)	Depth (mm)	Status	Remarks									

Roof Details Parameters Image



Binder for Roof Beam Support (250mm X 250mm)

Status

Remarks

OK

OK

Binder for Roof Beam Mid Span Support

Status

Remarks

OK

OK

Binder for Roof 8mm dia 125mm C/C

Status

Remarks

OK

OK

Overall Reamrks

Ok

Overall Work Status - Images

Photo 1 - Angle 1



Photo 2 - Angle 2



Signatures & Approval

Goutam Chari

Seal with signature of ULB Engineer
Name: _____
Contact no.: _____

**SUB. ASSISTANT ENGINEER
HALISAHAR MUNICIPALITY**

[Signature]
**Co-ordinator
Hijli INSPIRATION**

Checked & Verified

[Signature]
**Engineer (CIVIL)
Hijli INSPIRATION**

Signature of Engineer
HILLI INSPIRATION
Name: _____
Contact no.: _____