



ENGLISH BAZAR MUNICIPALITY

CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-00648 - Madhabnagar Badalmoni High School

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Madhabnagar Badalmoni High School	22.5797305 88.4135153	1	25.68	Sq/Meter



Project Details




Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	4	4	5	3

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	720	92	720	843	Maheshpur	

At the time of Roof Casting - Visit Details

Visit Date	10/12/2025											
Roof Beam Top Support (16 mm dia, 4 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Top Support Image	 <p>Lat: 24.98090 Long: 88.15131 Location: Maida, West Bengal</p>											
Roof Beam Bottom Support (16 mm dia, 2 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Bottom Support Image	 <p>Lat: 24.98048 Long: 88.15180 Location: Maheshpur P, West Bengal</p>											
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Mid Span Top Support Image	 <p>Lat: 24.98048 Long: 88.15180 Location: Maheshpur P, West Bengal</p>											
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Mid Span Bottom Support Image	 <p>Lat: 24.98048 Long: 88.15180 Location: Maheshpur P, West Bengal</p>											
Roof Details Parameters (8 mm dia 125 nos)	<table border="1"> <thead> <tr> <th>Diameter (mm)</th> <th>Depth (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> </tbody> </table>	Diameter (mm)	Depth (mm)	Status	Remarks							
Diameter (mm)	Depth (mm)	Status	Remarks									

<p>Details Parameters Image</p>	 <p>Lat: 24.98048 Long: 88.15180 Location: Maheshpur P, West Bengal</p>				
<p>Binder for Roof Beam Support (250mm X 250mm)</p>	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
<p>Binder for Roof Beam Mid Span Support</p>	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
<p>Binder for Roof 8mm dia 125mm C/C</p>	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
<p>Overall Remarks</p>	<p>Roof construction is not required as an existing roof is already in place.</p>				
<p>Overall Work Status - Images</p>					
<p>Photo 1 - Angle 1</p>	 <p>Lat: 24.98048 Long: 88.15180 Location: Maheshpur P, West Bengal</p>				
<p>Photo 2 - Angle 2</p>	 <p>Lat: 24.98250 Long: 88.15021 Location: Malda, Mokdumpur</p>				

Signatures & Approval


SAE (C)
 English Bazar Municipality
 MALDA

Seal with signature of ULB Engineer
 Name: Roanika Roy
 Contact no.: 8609887820


Co-ordinator
Hijli INSPIRATION

Checked & Verified


Engineer (Civil)
Hijli INSPIRATION

Signature of Engineer
 HILL INSPIRATION
 Name: _____
 Contact no.: _____