



ENGLISH BAZAR MUNICIPALITY  
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-00681 - Mokdumpur Aided Pry. School

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Mokdumpur Aided Pry. School	22.5797335 88.4135381	8	23.45	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	1	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khartan No.	Mouza	Possession Details (Owned by)
Danga	845	68	845	NIL	Mokdumpur	

At the time of Roof Casting - Visit Details

Site	26/02/2026											
Roof Beam Top Support (16 mm dia, 4 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Top Support Image												
Roof Beam Bottom Support (16 mm dia, 2 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Bottom Support Image												
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
2	16	OK	OK									
Roof Beam Mid Span Top Support Image												
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK			
Rod Nos.	Diameter (mm)	Status	Remarks									
4	16	OK	OK									
Roof Beam Mid Span Bottom Support Image												



**Binder for Roof Beam Support (250mm X 250mm)**

Status	Remarks
OK	OK

**Binder for Roof Beam Mid Span Support**

Status	Remarks
OK	OK

**Binder for Roof 8mm dia 125mm C/C**

Status	Remarks
OK	OK

**Overall Remarks**


Ok

**Overall Work Status - Images**

**Photo 1 - Angle 1**



**Photo 2 - Angle 2**



**Signatures & Approval**

*Signature*  
**SAE (C)**  
 English Bazar Municipality  
 MALDA

**Checked & Verified**  
*Signature*  
**Engineer (Civil)**  
 Hiji INSPIRATION

Seal with signature of ULB Engineer  
 Name: Soumen dranath Das.  
 Contact no.: 9434206589

*Signature*  
**Co-ordinator**  
**Hiji INSPIRATION**

Signature of Engineer  
 HILLI INSPIRATION

Name: \_\_\_\_\_  
 Contact no.: \_\_\_\_\_