



ENGLISH BAZAR MUNICIPALITY
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-00700 - Infront of Urban Health & Wellness Centre (UH&WC)

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Infront of Urban Health & Wellness Centre (UH&WC)	22.5797134 88.4135316	1	23.25	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	1	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	587	92	587	589	Mareshpur	

At the time of Roof Casting - Visit Details

Visit Date	11/12/2025										
Roof Beam Top Support (16 mm dia, 4 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
4	16	OK	OK								
Roof Beam Top Support Image											
Roof Beam Bottom Support (16 mm dia, 2 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
2	16	OK	OK								
Roof Beam Bottom Support Image											
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
2	16	OK	OK								
Roof Beam Mid Span Top Support Image											
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
4	16	OK	OK								
Roof Beam Mid Span Bottom Support Image											
Roof Details Parameters (8 mm dia 125 nos)	<table border="1"> <thead> <tr> <th>Diameter (mm)</th> <th>Depth (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> </tbody> </table>	Diameter (mm)	Depth (mm)	Status	Remarks						
Diameter (mm)	Depth (mm)	Status	Remarks								

its Parameters Image



Binder for Roof Beam Support (250mm X 250mm)

Status	Remarks
OK	OK

Binder for Roof Beam Mid Span Support

Status	Remarks
OK	OK

Binder for Roof 8mm dia 125mm C/C

Status	Remarks
OK	OK

Overall Reamrks


Ok

Overall Work Status - Images

Photo 1 - Angle 1



Photo 2 - Angle 2



Signatures & Approval

Romila Ray
SAE (C)
 English Bazar Municipality
 MALDA

Seal with signature of P.U.B Engineer
 Name: *Romila Ray*
 Contact no.: *8509887820*

M. S. S.
Co-ordinator,
Hijli INSPIRATION

Checked & Verified

Anand Mondal
Engineer (Civil)
Hijli INSPIRATION

Signature of Engineer
 HILLI INSPIRATION

Name: _____
 Contact no.: _____