



## JANGIPUR MUNICIPALITY

### CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01598 - Jangipur Harisava

#### Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Jangipur Harisava	22.5797475 88.4134717	9	22.5SqM	Sq/Meter

#### Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	1	1	2	1

#### Land Details

Classification	Plot No.	JI No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	1689	007	1689	1698	Jangipur	

At the time of Roof Casting - Visit Details

Visit Date	21/02/2026										
Roof Beam Top Support (16 mm dia, 4 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
4	16	OK	OK								
Roof Beam Top Support Image	 <p>Lat: 24.46536 Long: 88.07047 Location: Jangipur, Chhota</p>										
Roof Beam Bottom Support (16 mm dia, 2 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
2	16	OK	OK								
Roof Beam Bottom Support Image	 <p>Lat: 24.46536 Long: 88.07044 Location: Jangipur, Chhota</p>										
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
2	16	OK	OK								
Roof Beam Mid Span Top Support Image	 <p>Lat: 24.46541 Long: 88.07045 Location: Jangipur, Chhota</p>										
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
4	16	OK	OK								
Roof Beam Mid Span Bottom Support Image											

Roof Details Parameters Image



Binder for Roof Beam Support (250mm X 250mm)

Status	Remarks
OK	OK

Binder for Roof Beam Mid Span Support

Status	Remarks
OK	OK

Binder for Roof 8mm dia 125mm C/C

Status	Remarks
OK	OK

Overall Reamrks


Ok

Overall Work Status - Images

Photo 1 - Angle 1



Photo 2 - Angle 2



Signatures & Approval

Sub- Asst. Engineer  
Jangipur Municipality

Coordinator  
Hijli INSPIRATION

Checked & Verified

Engineer (Civil)  
Hijli INSPIRATION