



BIDHANNAGAR MC MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Back side of Balak Sangha club	22.5734762 88.4032322	38	25	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	5	3	4	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	NA	NA	NA	NA	NA	

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-04-06
Nearest location of CT/PT (approx)	Back side of Balak Sangha club
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model

Male Toilet Seats	0
Female Toilet Seats	0
Male Urinal	4
Female Urinal	0
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	0
No Of Urinal Seats	0
total Baths	0
Bath	0
Area	0
Cubical Male	0
Cubical Female	0
Cubical Urinal Seat Size	0
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Insufficient land

Name: Anshuman Mukherjee

Designation: SAE

Contact No: 8479960627


Date: _____

Name: Soumitra Bhattacharya

Designation: Project Coordinator


Contact No: 9674828902

Date: _____



Signature with stamp
 Sub-Assistant Engineer
 Bidhannagar Municipal Corporation.

Signature with stamp assigned by Hijli Inspiration



Lat: 22.5734762
Long: 88.4032322
Location: Kolkata, Kankurgachi



Lat: 22.5736578
Long: 88.4032919
Location: Kolkata, Bidhannagar

[Download PDF](#)
