



HABRA MUNICIPALITY

CONSTRUCTION SITE FIRST VISIT REPORT

First Visit : PROP-00285 - SREENAGAR SAKTI SANGHA

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
SREENAGAR SAKTI SANGHA	22.5797203 88.4135508	10	0.34	Acre



Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	NA	74	870	6078	JOYGACHI	

Construction Site First Visit Report

Foundation upto Tie beam with reinforcement details						
Visit Date	25/03/2026					
Earth Cutting (1200 x 1200 x 1000)	Column Nos.	Length (M)	Breath (M)	Height (M)	Status	Remarks
	10	1200	1200	1000	OK	OK
Earth Cutting Image	 <p>Lat: 22.83870 Long: 88.66557 Location: Habra, Gohalhati</p>					
Re-inforcement						
Footing (10 mm dia 10 nos both)	Rod Nos.	Diameter (M)	Status	Remarks		
	10	10	OK	OK		
Footing Image	 <p>Lat: 22.83881 Long: 88.66570 Location: Habra, Gohalhati</p>					

dia 6 nos)

Rod Nos.	Diameter (M)	Length (M)	Height (M)	Status	Remarks
6	12	250	250	OK	OK

Column Image



Tie beam
(12 mm dia 4 nos)

Rod Nos.	Diameter (M)	Length (M)	Breath (M)	Status	Remarks
4	12	250	250	OK	OK

Tie beam Image



Binder for Column 8 mm dia 175 mm C/C

Status	Remarks
OK	OK

Binder for Tie 8 mm dia 175 mm C/C

Status	Remarks
OK	OK

Overall Remarks

Ok

Overall Work Status - Images

Photo 1 - Angle 1



Photo 2 - Angle 2



