



SAINTHIA MUNICIPALITY
CONSTRUCTION SITE FIRST VISIT REPORT

First Visit : PROP-01601 - SARADA PALLY

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
SARADA PALLY	22.5797254 88.4135377	8	50	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	3	2	4	3

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	35	97	NA	NA	MURADIHI	

Construction Site First Visit Report

Foundation upto Tie beam with reinforcement details

Visit Date

02/03/2026

Earth Cutting
(1200 x 1200 x 1000)

Column Nos.	Length (M)	Breath (M)	Height (M)	Status	Remarks
10	1200	1200	1000	MISMATCH	Already constructed




Re-inforcement

Footing
(10 mm dia 10 nos
both)

Rod Nos.	Diameter (M)	Status	Remarks
10	10	MISMATCH	Already constructed


Footing Image



Column
(12 mm dia 6 nos)


Rod Nos.	Diameter (M)	Length (M)	Height (M)	Status	Remarks
6	12	250	250	MISMATCH	Already constructed

Column Image



Tie beam
(12 mm dia 4 nos)

Rod Nos.	Diameter (M)	Length (M)	Breath (M)	Status	Remarks
4	12	250	250	MISMATCH	Already constructed



Binder for Column 8 mm dia 175 mm C/C

Status

Remarks

PROBLEM

Already constructed

Binder for Tie 8 mm dia 175 mm C/C

Status

Remarks

OK


OK


Overall Reamrks

The slum had requested a toilet, so the municipality quickly completed the toilet work, and the quality of the work is good. The municipality has informed SUDA about the matter.


Overall Work Status - Images

Photo 1 - Angle 1





QR Code Board Image



Signatures & Approval

Sebarpan Datta
 ULTC

Seal with signature of ULB Engineer
 Name : _____
 Contact no. : _____

Checked & Verified
Atender
 Engineer (Civil)
 HILLI INSPIRATION

Signature of Engineer
 HILLI INSPIRATION
 Name : _____
 Contact no. : _____

M. S. L.
 Co-ordinator
 Hilli INSPIRATION