



FALAKATA

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Vivekananda more(dhupguri more), parengarper, Falakata	22.5640726 88.2386937	4	Vivekananda more(dhupguri more), parengarper, Falakata	Sq/ Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	2	2	3	2

Land Details

Classification	Plot No.	JI No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	1933/1936/1937	22	NA	6	parangarper	

Annexure-III (Joint Site Inspection Report)

Nearest location of CT/PT (approx)	Vivekananda more(dhugguri more), parengarper, Falakata
Toilet Type (Aspirational/Normal)	Aspirationa Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	3
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	SHG
Remarks	Na

Name:

Designation:

Signature with stamp

Contact No:

Date: _____

Name: TPA User

Designation: Inspector

Signature with stamp assigned by Hijli Inspiration

Contact No: 7475789756