



## DUBRAJPUR MUNICIPALITY

### CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-00059 - NEAR TOWN SAMITY CLUB

#### Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
NEAR TOWN SAMITY CLUB	22.5797324 88.4135151	12	0.04	Acre

#### Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	2	2

#### Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	4244	137	0	0	DUBRAJPUR	

#### Construction Site Second Visit Report

At the time of Roof Casting - Visit Details				
Visit Date	02/02/2026			
Roof Beam Top Support (16 mm dia, 4 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	4	16	OK	OK

Roof Beam Top Support Image



Roof Beam Bottom Support  
(16 mm dia, 2 nos.)

Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK

Roof Beam Bottom Support Image



Roof Beam Mid Span Top Support  
(16 mm dia 2 nos)

Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK

Roof Beam Mid Span Top Support Image



Roof Beam Mid Span Bottom Support  
(16 mm dia 4 nos)

Rod Nos.	Diameter (mm)	Status	Remarks
4	16	OK	OK

o 1 - Angle 1




Photo 2 - Angle 2



### Signatures & Approval

*[Handwritten Signature]*  
 S.A.E (UIDSSMT)  
 DUBRAJPUR MUNICIPALITY  
 Dubrajpur, Birbhum

Checked & Verified  
*Suprimo Ghosh*  
 Engineer (Civil)  
 Hilli INSPIRATION

Seal with signature of U/B Engineer

Name: *Rohit Ghosh*  
 Contact no.: *9832530829*

Signature of Engineer

HILLI INSPIRATION  
 Name: *SUPRIMO GHOSH*  
 Contact no.: *8622075848*

*[Handwritten Signature]*

Signature of Co-Ordinator

HILLI INSPIRATION  
 Co-ordinator  
 Hilli INSPIRATION