



# KALIMPONG MUNICIPALITY

## CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-00760 - DEEP JYOTI SANGH COMMUNITY HALL

### Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
DEEP JYOTI SANGH COMMUNITY HALL	26.3372844 89.4500297	19	TAMANG GAON, CHIBBO BUSTY	22.5 Sq/Meter

### Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Other	1	1	2	1

### Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	9124	56	N/A	972	N/A	

### Construction Site Second Visit Report

#### At the time of Roof Casting - Visit Details

Visit Date	06/04/2026			
Roof Beam Top Support (16 mm dia, 4 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	4	16	OK	OK

**Roof Beam Top Support Image**



**Roof Beam Bottom Support  
(16 mm dia, 2 nos.)**

Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK


**Roof Beam Bottom Support Image**



**Roof Beam Mid Span Top Support  
(16 mm dia 2 nos)**

Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK

**Roof Beam Mid Span Top Support Image**



**Roof Beam Mid Span Bottom Support**  
(16 mm dia 4 nos)

Rod Nos.	Diameter (mm)	Status	Remarks
4	16	OK	OK

**Roof Beam Mid Span Bottom Support Image**



**Roof Details Parameters**  
(8 mm dia 125 nos)

Diameter (mm)	Depth (mm)	Status	Remarks
8	125	OK	OK

**Roof Details Parameters Image**



**Binder for Roof Beam Support (250mm X 250mm)**

Status	Remarks
OK	OK

**Binder for Roof Beam Mid Span Support**

Status	Remarks
OK	OK

Binder for Roof 8mm dia 125mm C/C

Status

Remarks

OK

OK

Overall Remarks

All ok

Overall Work Status - Images

Photo 1 - Angle 1





Photo 2 - Angle 2



Signatures & Approval

*M. Ran*  
Sub Assistant Engineer  
Kalimpong Municipality

*S. Chatterjee*  
Co-ordinator  
Hijli INSPIRATION

Checked & Verified  
*A. S. Bider*  
Engineer (Civil)  
Hijli INSPIRATION