



JALPAIGURI MUNICIPALITY
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01469 - Sanitary Ground

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Sanitary Ground	26.5218112 88.7281895	8	Sanitary Ground	22.7

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	214	07	121	471	kharia	

Construction Site Second Visit Report

At the time of Roof Casting - Visit Details


Visit Date	14/01/2026			
Roof Beam Top Support (16 mm dia, 4 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	4	16	OK	OK



Roof Beam Bottom Support
(16 mm dia, 2 nos.)

Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK

Roof Beam Bottom Support Image



Roof Beam Mid Span Top Support
(16 mm dia 2 nos)


Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK

Roof Beam Mid Span Top Support Image



Roof Beam Mid Span Bottom Support
(16 mm dia 4 nos)

Rod Nos.	Diameter (mm)	Status	Remarks
4	16	OK	OK



Roof Details Parameters
(8 mm dia 125 nos)

Diameter (mm)	Depth (mm)	Status	Remarks
8	125	OK	OK

Roof Details Parameters Image



Binder for Roof Beam Support (250mm X 250mm)

Status	Remarks
OK	OK

Binder for Roof Beam Mid Span Support

Status	Remarks
OK	OK

Binder for Roof 8mm dia 125mm C/C

Status	Remarks
OK	OK

Overall Reamrks

Ok

Overall Work Status - Images



Lat: 26.52155
Long: 88.72791
Location: Jalpaiguri, West Bengal

Photo 2 - Angle 2



Lat: 26.52168
Long: 88.72803
Location: Jalpaiguri, West Bengal

Signatures & Approval

Manusree Das.

Seal with signature of **JUNIOR ENGINEER**
Name: _____
Contact no.: _____
JALPAIGURI MUNICIPALITY

Checked & Verified

Ashimodas

Engineer (Civil)
HILLI INSPIRATION

Signature of Engineer
HILLI INSPIRATION
Name: _____
Contact no.: _____

Siddhanta
Co-ordinator
HILLI INSPIRATION

Signature of Co-Ordinator
HILLI INSPIRATION