



JALPAIGURI MUNICIPALITY
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01488 - KUSTHO ASHRAM Unit -II (Female)

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
KUSTHO ASHRAM Unit -II (Female)	26.5346896 88.7334112	3	22.7	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	0	2	0	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	227	07	76	183	kharia	

Construction Site Second Visit Report

At the time of Roof Casting - Visit Details


Visit Date	14/01/2026			
Roof Beam Top Support (16 mm dia, 4 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	4	16	OK	OK

Roof Beam Bottom Support
(16 mm dia, 2 nos.)



Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK

Roof Beam Bottom Support Image



Rod Nos.	Diameter (mm)	Status	Remarks
2	16	OK	OK

Roof Beam Mid Span Top Support
(16 mm dia 2 nos)

Roof Beam Mid Span Top Support Image



Rod Nos.	Diameter (mm)	Status	Remarks
4	16	OK	OK

Roof Beam Mid Span Bottom Support
(16 mm dia 4 nos)



Roof Details Parameters
(8 mm dia 125 nos)

Diameter (mm)	Depth (mm)	Status	Remarks
8	125	OK	OK

Roof Details Parameters Image



Binder for Roof Beam Support (250mm X 250mm)

Status	Remarks
OK	OK

Binder for Roof Beam Mid Span Support

Status	Remarks
OK	OK

Binder for Roof 8mm dia 125mm C/C

Status	Remarks
OK	OK

Overall Reamrks

Ok

Overall Work Status - Images



Photo 2 - Angle 2



Signatures & Approval

Seal with signature of **JUNIOR ENGINEER**
Name: _____
Contact no. : _____
JALPAIGURI MUNICIPALITY

Checked & Verified

Engineer (Civil)
HILLI INSPIRATION

Signature of Engineer
HILLI INSPIRATION

Name : _____
Contact no. : _____

Co-ordinator
HILLI INSPIRATION

Signature of Co-Ordinator
HILLI INSPIRATION