



JANGIPUR MUNICIPALITY
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01620 - Kadikola

Location Details

| Name of the Location | Latitude & Longitude | Ward | Area | Area Unit |
|----------------------|--------------------------|------|----------|-----------|
| Kadikola | 22.5797256 88.4135397 | 21 | 35.7 SqM | Sq/Meter |





Project Details




| Proposed Project Type | Toilet Seat (Male) | Toilet Seat (Female) | Urinal Seat (Male) | Urinal Seat (Female) |
|-------------------------------|--------------------|----------------------|--------------------|----------------------|
| CT (Community Toilet Project) | 2 | 2 | 3 | 2 |

Land Details


| Classification | Plot No. | Jl No. | Dag No. | Khatian No. | Mouza | Possession Details (Owned by) |
|----------------|----------|--------|---------|-------------|-----------|-------------------------------|
| Bastu | 394 | 018 | 394 | 2578 | Joyrampur | |

At the time of Roof Casting - Visit Details


| Visit Date | 21/02/2026 | | | | | | | | | | |
|--|--|----------|---------------|--------|---------|---|----|----|----|--|--|
| Roof Beam Top Support (16 mm dia, 4 nos.) | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 4 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 4 | 16 | OK | OK | | | | | | | | |
| Roof Beam Top Support Image |  | | | | | | | | | | |
| Roof Beam Bottom Support (16 mm dia, 2 nos.) | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 2 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 2 | 16 | OK | OK | | | | | | | | |
| Roof Beam Bottom Support Image |  | | | | | | | | | | |
| Roof Beam Mid Span Top Support (16 mm dia 2 nos) | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 2 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 2 | 16 | OK | OK | | | | | | | | |
| Roof Beam Mid Span Top Support Image |  | | | | | | | | | | |
| Roof Beam Mid Span Bottom Support (16 mm dia 4 nos) | <table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Rod Nos. | Diameter (mm) | Status | Remarks | 4 | 16 | OK | OK | | |
| Rod Nos. | Diameter (mm) | Status | Remarks | | | | | | | | |
| 4 | 16 | OK | OK | | | | | | | | |
| Roof Beam Mid Span Bottom Support Image |  | | | | | | | | | | |

| Roof Details Parameters Image | |  | | | | |
|--|---------|--|--------|---------|----|----|
| Binder for Roof Beam Support (250mm X 250mm) | | <table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Status | Remarks | OK | OK |
| Status | Remarks | | | | | |
| OK | OK | | | | | |
| Binder for Roof Beam Mid Span Support | | <table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Status | Remarks | OK | OK |
| Status | Remarks | | | | | |
| OK | OK | | | | | |
| Binder for Roof 8mm dia 125mm C/C | | <table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table> | Status | Remarks | OK | OK |
| Status | Remarks | | | | | |
| OK | OK | | | | | |
| Overall Reamrks | | Ok | | | | |
| Overall Work Status - Images | | | | | | |
| Photo 1 - Angle 1 | |  | | | | |
| Photo 2 - Angle 2 | |  | | | | |

Signatures & Approval



Sub- Asst. Engineer
Jangipur Municipality



Page 3 of 3 Co-ordinator
Hijli INSPIRATION

Checked & Verified

Engineer (Civil)
Hijli INSPIRATION