



JANGIPUR MUNICIPALITY
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01643 - Joyrampur Rajpara

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Joyrampur Rajpara	22.5797357 88.4135074	1	35.7 SqM	Sq/Meter



Project Details




Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	3	2

Land Details


Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	576/1429	018	576/1429	1887	Joyrampur	

At the time of Roof Casting - Visit Details

Visit Date	23/02/2026			
Roof Beam Top Support (16 mm dia, 4 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	4	16	OK	OK
Roof Beam Top Support Image				
Roof Beam Bottom Support (16 mm dia, 2 nos.)	Rod Nos.	Diameter (mm)	Status	Remarks
	2	16	OK	OK
Roof Beam Bottom Support Image				
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	Rod Nos.	Diameter (mm)	Status	Remarks
	2	16	OK	OK
Roof Beam Mid Span Top Support Image				
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	Rod Nos.	Diameter (mm)	Status	Remarks
	4	16	OK	OK
Roof Beam Mid Span Bottom Support Image				

Roof Details Parameters Image	 <p>Lat: 24.47312 Long: 88.08528 Location: Jangipur,</p>				
Binder for Roof Beam Support (250mm X 250mm)	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
Binder for Roof Beam Mid Span Support	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
Binder for Roof 8mm dia 125mm C/C	<table border="1"> <thead> <tr> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Status	Remarks	OK	OK
Status	Remarks				
OK	OK				
Overall Remarks	Ok				
Overall Work Status - Images					
Photo 1 - Angle 1	 <p>Lat: 24.47310 Long: 88.08512 Location: Jangipur,</p>				
Photo 2 - Angle 2	 <p>Lat: 24.47226 Long: 88.08351 Location: Jayrampur P,</p>				

Signatures & Approval


 Sub-Asst. Engineer
 Jangipur Municipality


 Page 3 of 3
 Co-ordinator
 Hijli INSPIRATION

Checked & Verified

 Engineer (Civil)
 Hijli INSPIRATION