



JANGIPUR MUNICIPALITY
CONSTRUCTION SITE SECOND VISIT REPORT

Second Visit : PROP-01645 - Barej More at Raghunathganj

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Barej More at Raghunathganj	22.5797316 88.4135544	19	35.7 SqM	Sq/Meter





Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	3	2

Land Details

Classification	Plot No.	JI No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	88	1206	88	Basudevpur	Basudevpur	

At the time of Roof Casting - Visit Details

Visit Date	21/02/2026										
Roof Beam Top Support (16 mm dia, 4 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
4	16	OK	OK								
Roof Beam Top Support Image											
Roof Beam Bottom Support (16 mm dia, 2 nos.)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
2	16	OK	OK								
Roof Beam Bottom Support Image											
Roof Beam Mid Span Top Support (16 mm dia 2 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>2</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	2	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
2	16	OK	OK								
Roof Beam Mid Span Top Support Image											
Roof Beam Mid Span Bottom Support (16 mm dia 4 nos)	<table border="1"> <thead> <tr> <th>Rod Nos.</th> <th>Diameter (mm)</th> <th>Status</th> <th>Remarks</th> </tr> </thead> <tbody> <tr> <td>4</td> <td>16</td> <td>OK</td> <td>OK</td> </tr> </tbody> </table>	Rod Nos.	Diameter (mm)	Status	Remarks	4	16	OK	OK		
Rod Nos.	Diameter (mm)	Status	Remarks								
4	16	OK	OK								
Roof Beam Mid Span Bottom Support Image											

Roof Details Parameters Image



Binder for Roof Beam Support (250mm X 250mm)

Status	Remarks
OK	OK

Binder for Roof Beam Mid Span Support

Status	Remarks
OK	OK

Binder for Roof 8mm dia 125mm C/C

Status	Remarks
OK	OK

Overall Reamrks


Ok

Overall Work Status - Images


Photo 1 - Angle 1




Photo 2 - Angle 2



Signatures & Approval


Sub- Asst. Engineer
Jangipur Municipality


Page 3 of 3 Co-ordinator
Hijli INSPIRATION

Checked & Verified

Engineer (Civil)
Hijli INSPIRATION