



CONTAI MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
csa maidan	22.5796959 88.4135232	17	near csa maidan	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	3	1	6	3

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	119	264	65	65	karluli	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-08
Nearest location of CT/PT (approx)	csa maidan
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	6
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Submersible pump
Operation and Maintenance Plan	Third-party
Remarks	Third party

Name: Dilip Kumar Bera

Designation: SAE

Contact No: 9732596585

Date: _____

Name: Sumit Saha

Designation: Project Coordinator

Signature with stamp

Signature with stamp assigned by Hijli Inspiration

Site Image

