



CONTAI MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
NEAR JUNCTION POINT CONTAI BELDA ROAD & N.H 116B	22.5797586 88.4135064	19	CONTAI BELDA ROAD	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	3	2	3	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Path	157	265	157	157	KISHORENGAR	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-08
Nearest location of CT/PT (approx)	NEAR JUNCTION POINT CONTAI BELDA ROAD & N.H 116B
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	3
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Submersible pump
Operation and Maintenance Plan	Other (specify)
Remarks	School

Name: Dilip Kumar Bera

Designation: SAE

Contact No: 9732596585

Date: _____

Name: Sumit Saha

Designation: Project Coordinator

Signature with stamp

Signature with stamp assigned by Hijli Inspiration

Site Image

