



## BERHAMPORE

### JOINT SITE INSPECTION REPORT

#### Annexure-III

#### Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Near Boro Raj Bari	24.0871402 88.2538237	1	24.0	Sq/Meter

#### Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Bastu	2	2	0	0

#### Land Details

Classification	Plot No.	JI No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	838	102	838	1188	Cossimbazar	

## Annexure-III (Joint Site Inspection Report)

Visit Date	2025-06-18
Nearest location of CT/PT ( approx )	Near Boro Raj Bari
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	0
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Well
Operation and Maintenance Plan	Other (specify)
Remarks	Cancel

Name: Nirmalendu Mandal

Designation: SAE

Contact No: 9475070600

Date: \_\_\_\_\_

Name: Abhik Majumdar

Designation: Civil Engineer

Signature with stamp

  
**S.A.E**  
 Berhampore Municipality



Signature with stamp assigned by Hijli Inspiration

Site Image

