



CONTAI MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Darua Hat	22.5797349 88.4135014	1	darua	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	3	9	9	9

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	0	475	0	0	uttar darua	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-08
Nearest location of CT/PT (approx)	Darua Hat
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No D
Male Toilet Seats	3
Female Toilet Seats	9
Male Urinal	9
Female Urinal	9
Male Bath	1
Female Bath	1
Children Feed	1
Children Feed	1
No Of Toilet Seats	12
No Of Urinal Seats	18
total Baths	2
Bath	0
Area	19m x 11m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Third-party
Remarks	Third party

Name: Dilip Kumar Bera

Designation: SAE

Contact No: 9732596585

Date: _____

Name: Prabir Mukherjee

Designation: Civil Engineer

Signature with stamp

Signature with stamp assigned by Hijli Inspiration

Site Image

