



CONTAI MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Contai Sub divisional Hospital	22.5796982 88.413524	1	Hospital Area	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	3	3	2	3

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	0	475	0	0	Uttar Darua	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-08
Nearest location of CT/PT (approx)	Contai Sub divisional Hospital
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT - Plan no 5
Male Toilet Seats	3
Female Toilet Seats	3
Male Urinal	2
Female Urinal	3
Male Bath	1
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	6
No Of Urinal Seats	5
total Baths	0
Bath	1
Area	8.1m x 8m
Cubical Male	1200 x 1350 mm
Cubical Female	1200 x 1350 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Third-party
Remarks	Third party

Name: Dilip Kumar Bera

Designation: SAE

Contact No: 9732596585

Date: _____

Name: Prabir Mukherjee

Designation: Civil Engineer

Signature with stamp

Signature with stamp assigned by Hijli Inspiration

Site Image

