



BAIDYABATI MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Kristi Chakra Gobindanagar, Baidyabati, Hooghly	22.7971486 88.330579	17	12	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	1	0	2	0

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	1707	4	2252	1331	Dirghanga	Kristi Chakra.

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-06-26
Nearest location of CT/PT (approx)	Kristi Chakra Gobindanagar, Baidyabati, Hooghly
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	User Group
Remarks	Average users 50

Name: Ujjwal Seth


Designation: SAE

Contact No: 7980428592

Date: _____

Name: Hiji Inspiration

Designation: Admin


 Signature with stamp **Ujjwal Seth**
Sub-Assistant Engineer
Baidyabati Municipality

Checked & Verified

 Signature with stamp assigned by Hiji **Prolem Mukhopadhyay**
Engineer (CIVIL)
Hiji Inspiration

Site Image

