



BAIDYABATI MUNICIPALITY  
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Nibaran Chandra G.S. F. P School	22.7970935 88.3293511	17	12	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	1	0	3	0

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	1188	4	1184	827/509	Dirghanga	Nibaran Chandra G.S.F.P School.

**Annexure-III (Joint Site Inspection Report)**

Visit Date	2025-06-26
Nearest location of CT/PT ( approx )	Nibaran Chandra G.S. F. P School
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	3
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Insufficient space (cancelled)

Name: Ujjwal Seth


Designation: SAE


Contact No: 7990428592

Date: \_\_\_\_\_

Name: Him Inspiration

Designation: Admin

  
 Signature with stamp  
**Sub-Assistant Engineer**  
**Baidyabati Municipality**

Checked & Verified  
  
 Signature with stamp assigned  
**Engineer (Civil)**  
**HIM INSPIRATION**

Site Image

