



RISHRA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
BESIDE MAITREE PATH MELA GROUND	22.7288425 88.3441211	4	MAITREE PATH MELA GROUND	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	1	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	12709	15	12709	10219	Maresh	

S.A.E.
Rishra Municipality

Checked & Verified

Engineer (Civil) 8/11/21
MHA INSPIRATION

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-11-07
Nearest location of CT/PT (approx)	BESIDE MAITREE PATH MELA GROUND
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	1
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Availability of surface water
Operation and Maintenance Plan	Third-party
Remarks	Third party agency

Name: Tanbir Hossain

Designation: Other

Contact No: 8240118189


Date: _____


 SAE
 Rishra Municipality


Signature with stamp

Checked & Verified


Site Image



Lat: 22.7270048
Long: 88.3442861
Location: Hooghly, Rishra



Lat: 22.7269484
Long: 88.3443388
Location: Hooghly, Rishra

S. Saha
S.A.E.
Rishra Municipality

Checked & verified
Pradip Mukherjee
Engineer (Civil) *8/11/25*
M&R INSPECTION