



TUFANGANJ

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Near Haridham HS school	26.3272447 89.6676364	12	New Town, Tufanganj	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Other	2	2	4	3

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	263	71	6379	3316	Andaranfulbari-1	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-06-12
Nearest location of CT/PT (approx)	Near Haridham HS school
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No G
Male Toilet Seats	2
Female Toilet Seats	2
Male Urinal	4 3
Female Urinal	2
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	4
No Of Urinal Seats	5
total Baths	0
Bath	0
Area	7m x 5.1m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Availability of surface water
Operation and Maintenance Plan	Other (specify)
Remarks	Maintenance by school committee

Name: Samit Saha

Designation: SAE

Contact No: 9832309221

Date: 13.06.25

Name: Dibyendu Bhattacharjee & Abhik Majumdar

Designation: Coordinator & civil Engineer

Samit Saha

D. Bharami

Signature with stamp

S.A.E.
Tufanganj Municipality

Sanitary Inspector
Tufanganj Municipality

S. Bhattacharjee

Abhik Majumdar

Signature with stamp assigned by Hiji Inspiration

Site Image

