

Site inspection Report for construction of CT/PT

Gyeshpur  
18

Kulia Path, <sup>near</sup> Tapur Bari

PT

ULB

D.No - 1405 K no - 02  
JL no - 83 Mouza - Kulia

Yes (ULB)

NO

2

2

3

2

Normal 'G'

Yes, Survey not done in

Yes

3rd party

9339575573

Pradip Kumar

Supervisor

21/11/2019

Handwritten signature

Checked & Verified

Engineer (Civil)  
MIS INSPECTION