


Annexure-III

Site Inspection Report for construction of CT/PT

Date :

| | | |
|--|--|-----------------------------|
| ULB Name | Garulia | |
| Ward No | 1 | |
| Name of the proposed site | Santingar gosh para, Jogajog chub | |
| Address | Ward - 1, Garulia | |
| Category CT/PT | PT, | |
| Necessary Land Details | Whether the Land is belongs to the ULB/Other (If Other please specify) | Club, |
| | Dag No., Khatian No., J.L. No. & other plot information. | Dag No - 113 (P), 114, |
| | No objection Certificate received from the concerned authority | No |
| Nearest location of CT/PT (approx distance in meter) | | |
| Proposed no of Toilet seats | Male | |
| | Female | |
| Proposed no of Urinal seats | Male | |
| | Female | |
| To be constructed as Aspirational Toilet or Normal Toilet (only) | Aspirational/Normal | |
| Area required for Public Toilets | 4 to 5 sq. meters per 10 toilet seats: Min. 1.5 m x 1.2 m | (checked) |
| Area requirement details in sq mm for Community Toilets | Toilet Cubical (Optimum=900x1200, Minimum=750x900) | |
| | Urinal (Minimum=500x600) | |
| Space identified for installation of Soakpit and Soak Well | | |
| Availability of surface water/piped water supply (in details) | | |
| Operation and Maintenance plan in detail | | |
| Remarks if any: | Land space problem. | |
| Representative assigned from Hijli for the site inspection | Name & Designation | Prabin Mukherjee (Engineer) |
| | Contact No | 9339875575 |
| | Signature with Seal | |
| Representative assigned from the ward for the site inspection | Name & Designation | Susanta Saha (S.A.E.) |
| | Contact No | 9820188839 |
| | Signature with Seal | |

Checked & Verified

 Prabin Mukherjee
 Engineer
 15/05/2017