



Annexure-III

Site Inspection Report for construction of CT/PT

Date:

15/01/25

| | | |
|--|---|--|
| ULB Name | Dainhat Municipality | |
| Ward No | 08 | |
| Name of the proposed site | Near Siddeswari Temple, Bera | |
| Address | Near Siddeswari Temple, Bera Ward NO - 08 | |
| Category CT/PT | INS (ICDS) | |
| Necessary Land Details | Wheather the Land is belongs to the ULB/Other (If Other please specify) | ULB |
| | Dag No., Khatian No., J.L. No. & other plot information. | JL NO - 27, Plot NO - 858 MOUZA - Bera. |
| | No objection Certificate received from the concerned authority (Yes/No) | yes. |
| Nearest location of CT/PT (approx distance in meter) | NO. | |
| Proposed no of Toilet seats | Male | 2 |
| | Female | 2 |
| Proposed no of Urinal seats | Male | 3 |
| | Female | 2 |
| To be constructed as Aspirational Toilet or Normal Toilet (only) | Aspirational/Normal | |
| Area rquired for Public Toilets | 4 to 5 sq. meters per 10 toilet seats: Min. 1.5 m x 1.2 m | Model - B1 |
| Area requirement details in sq mm for Community Toilets | Toilet Cubical (Optimum=900x1200, Minimum=750x900) | |
| | Urinal (Minimum=500x600) | |
| Space identified for installation of Soakpit and Soak Well | yes. | |
| Availability of surface water/piped water supply (in details) | Available | |
| Operation and Maintenance plan in detail | 3rd party | |
| Remarks if any: | | |
| Representative assigned from Hijli Inspiration for the site inspection | Name & Designation | |
| | Contact No | 9339875575 |
| | Signature with Seal |  |
| Representative assigned from the ULB for the site inspection | Name & Designation | SAYAN MUKHERJEE S.A.-B |
| | Contact No | 6204558601 |
| | Signature with Seal |  |

Sub-Assistant Engineer
Dainhat Municipality