



BHADRESWAR MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Tantipara	22.8371923 88.3671476	9	142.50	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	4	4	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	154	10	154	1296	Telintipara	


SI / SA / CLERK
SANTARY DEPARTMENT
BHADRESWAR MUNICIPALITY

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-10
Nearest location of CT/PT (approx)	Tantipara
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	2
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Solar Pump
Operation and Maintenance Plan	Other (specify)
Remarks	Cancel for existing Community Toilet

Name: Swapan Das

Designation: SAE

Contact No: 9007493077


Date: _____

Name: Prabir Mukhopadhyay

Designation: Civil Engineer


 Signature with stamp **S. A. E. (H.F.A.)**
BHADRESWAR MUNICIPALITY

Checked & Verified


 Signature with stamp assigned by Hijli Insp **INSPIRATION**
Engineer (Civil)

Site Image



Lat: 22.8372693
Long: 88.3666935
Location: Chinsurah, Mankundu



Lat: 22.8367901
Long: 88.3674047
Location: Chinsurah, Mankundu