



CHAKDAHA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
MAITRA SANGHA	22.5797057 88.4135304	21	245	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	1	1	2	1

Land Details

Classification	Plot No.	JI No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	0	23	1014	125	KAJIPARA	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-01
Nearest location of CT/PT (approx)	MAITRA SANGHA
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	②
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Well
Operation and Maintenance Plan	ULB
Remarks	Rejected

Name: Nabamita Sarkar


Designation: SAE

Contact No: +917001736011


Date: _____

Name: Prabir Mukherjee

Designation: Civil Engineer



 Signature with stamp

Checked & Verified


 Signature with stamp assigned by Hill Inspiration
 HILL INSPIRATION

Site Image



[Handwritten signature]