



CHAKDAHA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Goti Club	22.5797098 88.413511	6	366	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	1	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	na	32	115	168	Jashra	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-01
Nearest location of CT/PT (approx)	Goti Club
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	—
Female Toilet Seats	—
Male Urinal	② —
Female Urinal	—
Male Bath	—
Female Bath	—
Children Feed	—
Children Feed	—
No Of Toilet Seats	—
No Of Urinal Seats	—
total Baths	—
Bath	—
Area	—
Cubical Male	—
Cubical Female	—
Cubical Urinal Seat Size	—
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Well
Operation and Maintenance Plan	ULB
Remarks	No need

Name: Nabamita Sarkar

Designation: SAE

Contact No: +91 94743 39524

Date: _____

Name: Prabir Mukherjee

Designation: Civil Engineer


Signature with stamp

Nabamita Sarkar
Checked & Verified

Engineer (C.E.)
Hijli INSPIR
Prabir Mukherjee

Signature with stamp assigned by Hijli Inspiration

Site Image



Handwritten signature