



CHAKDAHA MUNICIPALITY  
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Kaya Colony near Agramami Club	22.5797169 88.4135184	15	123	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	1	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	na	21	125	715	LALPUR	

**Annexure-III (Joint Site Inspection Report)**

Visit Date	2025-07-01
Nearest location of CT/PT ( approx )	Kaya Colony near Agragrami Club
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	✓
Female Toilet Seats	-
Male Urinal	② ✓
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Well
Operation and Maintenance Plan	Other (specify)
Remarks	Rejected

Name: Nabamita Sarkar

Designation: SAE

Contact No: 9474339524

Date: \_\_\_\_\_

Name: Prabir Mukherjee

Designation: Project Coordinator

*Sarkar*


Signature with stamp

**Checked & Verified**

*Prabir Mukherjee*  
Engineer (Civil)

Signature with stamp assigned by Hiji Inspiration

Site Image



*Handwritten signature*