

Annexure-III

Site Inspection Report for construction of CT/PT

Date: 28/11/21

Location of the proposed	Ranaghat Municipality
	13
	At kamarpukur more
	At kamarpukur more ward no 13
Type of CT/PT	PT
Location and Details	ULB Land
Whether the Land is belong to the ULB/Other (If Other please specify)	
Dag No., Khatian No., J.L.No. & other plot information.	Mouza with JL : 156, Nasra Plot no: 876 Kh no: 4213
No objection Certificate received from the concerned authority (Yes/No)	Yes
Nearest location of CT/PT (approx distance in meter)	
Proposed no of Toilet seats	Male
	Female
Proposed no of Urinal seats	Male
	Female
To be constructed as Aspirational Toilet or Normal Toilet (only)	Normal
Area required for Public Toilets	1 to 5 sq. meters per 10 toilet seats: Min. 1.5m x 1.2m
Area requirement details sq.m for Community Toilet	Toilet Cubical (Optimum=900x1200, Minimum=750x900) Urinal (Minimum=500x600)
Space identified for installation of Soak pit and Soak Well	1. Yes 2. No
Availability of surface water/piped water supply (in detail)	Available
Operation and Maintenance plan in detail	
Representative assigned from the inspiration for inspection	Name & Designation: Prabir Mukherjee Civil Engineer Hiji INSPIRATION Contact No: 9339875575 Signature with Seal: <i>Prabir Mukherjee</i> Checked & Verified: <i>Prabir Mukherjee</i> Engineer (Civil) Hiji INSPIRATION
Representative assigned from the ULB for the site inspection	Name & Designation: Sudipto Mukherjee Contact No: 7001323900 Signature with Seal: <i>Sudipto Mukherjee</i>

Rejected for insufficient of card

*Sudipto*  
NODAL ENGINEER  
SOLID WASTE MANAGEMENT  
RANAGHAT MUNICIPALITY

*Sudipto*  
Chairman  
Ranaghat Municipality

Rejected