



TUFANGANJ

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Madan Mohan mandir	26.3168785 89.6696723	4	Madan mohan Mandir	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Danga	2	2	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	0	71	0	0	Andaranfulbari-1	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-06-12
Nearest location of CT/PT (approx)	Madan Mohan mandir
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Availability of surface water
Operation and Maintenance Plan	Other (specify)
Remarks	Maintenance by mandir committee

Name: Samit Saha


Designation: SAE

Contact No: 9832309221


Date: 13.06.25

Name: Dibyendu Bhattacharjee & Abhik Majumdar

Designation: Coordinator & civil Engineer


 Signature with stamp
 S.A.E.
 Tufanganj Municipality


 Signature with stamp assigned by Hiji Inspiration


 Sanitary Inspector
 Tufanganj Municipality

