

Annexure-III (Joint Site Inspection Report)

| | |
|--------------------------------------|--------------------------------|
| Visit Date | 2025-07-02 |
| Nearest location of CT/PT (approx) | Pranabananda Pally, Kenduadihi |
| Toilet Type (Aspirational/Normal) | Normal Toilet |
| Model Name | CT/PT - Model No F |
| Male Toilet Seats | 1 |
| Female Toilet Seats | 1 |
| Male Urinal | 2 |
| Female Urinal | 1 |
| Male Bath | 0 |
| Female Bath | 0 |
| Children Feed | 0 |
| Children Feed | 0 |
| No Of Toilet Seats | 2 |
| No Of Urinal Seats | 3 |
| total Baths | 0 |
| Bath | 0 |
| Area | 5m x 4.5m |
| Cubical Male | 1200 x 1000 mm |
| Cubical Female | 1600 x 1200 mm |
| Cubical Urinal Seat Size | 600/500 |
| Space for Soakpit/Soak Well | Available |
| Water Availability (Details) | Submersible pump |
| Operation and Maintenance Plan | User Group |
| Remarks | User group |

Name: Samit Chand

Designation: SAE

Contact No: 9382385648

Date: _____

Name: Prabir Mukherjee

Designation: Civil Engineer

Signature with stamp

K. Das
S.A.E.

Bankura Municipality
Checked & Verified

A. Janda

Engineer (Civil)
Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration