



BANKURA MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
SIMULDANGA	22.5797321 88.413526	14	SIMULDANGA	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	1	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	NA	NA	NA	NA	NA	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-02
Nearest location of CT/PT (approx)	SIMULDANGA
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	2
Female Toilet Seats	2
Male Urinal	1
Female Urinal	1
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	4
No Of Urinal Seats	2
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Submersible pump
Operation and Maintenance Plan	User Group
Remarks	User group

Name: Samit Chand

Designation: SAE

Contact No: 93823 85648

Date: _____

Name: Prabir Mukherjee

Designation: Civil Engineer

Signature with stamp

Signature with stamp assigned by Hijli Inspiration

