



TEST MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
HC Block	22.5734621 88.4190285	5	32	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Bastu	4	4	4	4

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	2	5	4	5	4	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-06-11
Nearest location of CT/PT (approx)	HC Block
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No B
Male Toilet Seats	3
Female Toilet Seats	5
Male Urinal	4
Female Urinal	5
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	5
No Of Urinal Seats	8
total Baths	0
Bath	0
Area	14m x 11m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	SHG
Remarks	Ok

Name: Ashok Kumar

Designation: AE

Contact No: 7894563421

Date: _____

Name: TPA User

Designation: Inspector

Signature with stamp

Signature with stamp assigned by Hijli Inspiration

Site Image

