



9

KALNA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
DANGAPARA	23.2273035 88.3601101	2	63.25	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	3	3	3	3

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	NA	164	NA	NA	KALNA	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-23
Nearest location of CT/PT (approx)	DANGAPARA
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	—
Female Toilet Seats	—
Male Urinal	3
Female Urinal	—
Male Bath	—
Female Bath	—
Children Feed	—
Children Feed	—
No Of Toilet Seats	—
No Of Urinal Seats	—
total Baths	—
Bath	—
Area	—
Cubical Male	—
Cubical Female	—
Cubical Urinal Seat Size	—
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Cancel due to insufficient space and near to water body

Name: Sourav Basu

Designation: SAE

Contact No: 7980294582

Date: _____

Name: Abhik Majumdar

Signature with stamp

Sourav Basu
Urban Infrastructure Expert
Kalna Municipality

Checked & Verified

Abhik Majumdar
Engineer (Civil)
Hiji INSPIRATION

Signature with stamp assigned by Hiji Inspiration

