



CHAMPDANI MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
angus line area	22.8175753 88.3468202	11	line area	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	3	3	0	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	2063	21	2063	2063	Gourhati	

Visit Date	2025-07-22
Nearest location of CT/PT (approx)	angus line area
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	0
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Cancel due to NOC

Name: Girish Chandra Ranu


Designation: AE

Contact No: 8016238874


Date: _____

Name: Prabir Mukhopadhyay

Designation: Civil Engineer


 Signature with stamp Assistant Engineer
 Champdany Municipality

Checked & Verified



Engineer (Civil)

HILTI INCORPORATION

Signature with stamp assigned by Hilti Inspiration

Site Image

