



CHAMPDANI MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
HINDU LINE II	22.8069051 88.3465307	9	NEAR NORTH BROOK JUTE MILL GATE	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	3	3	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	3438/3199	21	3438/3199	1026/7	GOURHATI	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-22
Nearest location of CT/PT (approx)	HINDU LINE II
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No A
Male Toilet Seats	2
Female Toilet Seats	3
Male Urinal	2
Female Urinal	3
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	5
No Of Urinal Seats	5
total Baths	0
Bath	0
Area	7.5m x 7.7m
Cubical Male	1200 x 1000 mm
Cubical Female	1800 x 1000 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	ULB
Remarks	NA

Name: Girish Chandra Ranu

Designation: AE

Contact No: 8016238874

Date: _____

Name: Prabir Mukhopadhyay / ABHIK MAJUMDAR

Designation: Civil Engineer


Signature with stamp

Assistant Engineer
Champdany Municipality


Checked & Verified


 Engineer (Civil)
 Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration



Lat: 22.807802
Long: 88.3471564
Location: Hooghly, Champdani



Lat: 22.807802
Long: 88.3471564
Location: Hooghly, Champdani