


Annexure-III (Joint Site Inspection Report)

Visit Date	2025-07-31
Nearest location of CT/PT (approx)	Near ANPC Road Sweet Shop
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	1
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Availability of surface water
Operation and Maintenance Plan	Other (specify)
Remarks	Cancel due to insufficient space


Sub Assistant Engineer
 Ranaghat Municipality

Name: Sudipta Mukharjee

Designation: SAE


Contact No: 9001323900

Date: _____

Name: Abhik Majumdar

Designation: Civil Engineer

Signature with stamp

Checked & Verified

Engineer (Civil)
 Signature with stamp assigned by Hiji Inspiration