



TAMRALIPTA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Padumbasan Khudiram Pry School	22.2738526 87.9262795	11	18	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	1	1	1	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	5532	144	5532	1034	Pdumbasan	

K. Panja
02.12.25
K. PANJA
Sub-Assistant Engineer
Tamralipta Municipality

Checked & Verified
P. Pradhan
Engineer (Civil)
Hijli INSPIRATION

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-12-02
Nearest location of CT/PT (approx)	Padumbasan Khudiram Pry School
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT - Plan no 1
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	1
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	2
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1500 x 1350 mm
Cubical Female	1200 x 1350 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Well
Operation and Maintenance Plan	Other (specify)
Remarks	Other

Name: K.panja


Designation: SAE

Contact No: +919474057408

Date: _____

Name: Sumit Saha

Signature with stamp


 K. PANJA
 Sub-Inspector
 Municipal Corporation

Checked & Verified