



**TAMRALIPTA MUNICIPALITY**  
**JOINT SITE INSPECTION REPORT**

**Annexure-III**

**Location Details**

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Daharpur	22.2848613 87.9137802	16	150	Sq/Meter

**Project Details**

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	2	2	2	2

**Land Details**

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	279	276	279	111	Daharpur	

*18/02/25*

**K. PANJA**  
Sub-Assistant Engineer  
Tamralipta Municipality

Checked & Verified  
*Prafulla Kumar Pradhan*  
Engineer (Civil)  
Hijli INSPIRATION

## Annexure-III (Joint Site Inspection Report)

Visit Date	2025-12-02
Nearest location of CT/PT ( approx )	Daharpur
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Availability of surface water
Operation and Maintenance Plan	Other (specify)
Remarks	Institute

Name: K.Panja

Designation: SAE


Contact No: +919474057408

Date: \_\_\_\_\_

Name: Prabir Mukherjee


Designation: Civil engineer

Signature with stamp


  
**K. PANJA**  
 Sr. Assistant Engineer  
 Tarn Tarnpota Municipality

Signature with stamp assigned by Hiji Inspiration


**Checked & Verified**

  
 Prabir Mukherjee  
 Engineer (Civil) 21/12/25

Site Image



Lat: 22.2848395  
Long: 87.9137333  
Location: Tamruk, Daharpur



Lat: 22.2848006  
Long: 87.9136579  
Location: Uttar Chara Sankarara, West Bengal

*K. Panja* 02.12.25  
K. PANJA  
Sub-Assistant Engineer  
Tarnakata Municipality

Checked & Verified  
*Prullu Mukherjee*  
Engineer (Civil)  
Hill INSPECTION