



JIAGANJ-AZIMGANJ MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
RANI DHANYA KUMARI COLLEGE	24.2439341 88.2726056	3	R.D.K. COLLEGE ,JIAGANJ	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	4	4	4	4

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	288,289,290,292,295 &296	209	288,289,290,292,295 &296	123	THIKAMAHAL NEJAMATGANJ	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-11-12
Nearest location of CT/PT (approx)	RANI DHANYA KUMARI COLLEGE
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No A
Male Toilet Seats	2
Female Toilet Seats	3
Male Urinal	4
Female Urinal	3
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	5
No Of Urinal Seats	5
total Baths	0
Bath	0
Area	7.5m x 7.7m
Cubical Male	1200 x 1000 mm
Cubical Female	1800 x 1000 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Toilet maintenance by college authority

Name: Kousik Pandey

Designation: SAE


Contact No: 7001198093

Date: _____

Name: Abhik Majumdar

Designation: Civil Engineer

Signature with stamp


Technical Supervisor
Jiaganj-Azimganj Municipality

Signature with stamp assigned by Hijli Inspiration

Site Image



Lat: 24.2439341
Long: 88.2726056
Location: জিয়াগঞ্জ, বালিগ্রাম



Lat: 24.2440045
Long: 88.2727338
Location: জিয়াগঞ্জ, বালিগ্রাম