



HABRA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
MILAN SANGHA	22.8396138 88.6705708	11	0.004	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	3	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	NA	80	56	5287	NAGARTHUBA	



Annexure-III (Joint Site Inspection Report)

Visit Date	2025-11-28
Nearest location of CT/PT (approx)	MILAN SANGHA
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	O&M by club

Name: Pankaj Ghosh

Designation: SAE

Contact No: 7679434985

Date: _____

Name: Probir Mukhopadhyay

Designation: Engineer

Signature with stamp

P Ghosh
28/11/25
Sub-Assistant Engineer
HABRA MUNICIPALITY

Checked & Verified
Probir Mukhopadhyay
28/11/25
Engineer (Civil)
Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration



