



HABRA MUNICIPALITY  
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Banipur loko utsav-I	22.8390575 88.6525521	21	0.005	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	3	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	NA	84	721	2226	ASRAFABAD	

Checked by  
*P. N. Saha*  
28/11/25

## Annexure-III (Joint Site Inspection Report)

Visit Date	2025-12-04
Nearest location of CT/PT ( approx )	Banipur loko utsav-I
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	3
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Tube-well
Operation and Maintenance Plan	Other (specify)
Remarks	Cancel due to lack regular users

Name: Pankaj

Designation: SAE


Contact No: 7679434985

Date: \_\_\_\_\_

Name: Prabir Mukherjee


Designation: Engineer

Signature with stamp





28/11/25

Sub-Assistant Engineer  
HABRA MUNICIPALITY



Signature with stamp assigned by Hijli Inspiration

Site Image



Checked & Verified  
*Prabin Mahapatra* 28/11/24  
PROBIP CONSULTANTS  
Engineers  
INSPIRATION